Page 1 of 2

71111



# TENNESSEE DEPARTMENT OF TRANSPORTATION EROSION PREVENTION/SEDIMENT CONTROL INSPECTION REPORT

Reason For Inspection:

Predicted Precipitation Source:

1st Weekly

2nd Weekly

											DATE:	LT-11
State Route	(SR) / US Rou	ite or Road Na	me and De	escription:			Are correcti	ive actions	required by	this inspec	ction report (Y/N):	
Ciato rioato	Wolf River Blvd.								YES	5		
County(ies):		TDOT PIN:		NPDES Per	rmit (NOC)	#:	Number of	New	Number of	Recurring	Number of New	Number of Un-Corrected
2 2 20		AC ANOTHER					Corrective /	Actions:	Corrective .	Actions:	Sediment Releases:	Sediment Releases:
Sh	nelby	1016	15		FNR153299	)						
<b>TDOT Cons</b>	truction No.:	TDOT Contra	ct No.:	Contractor:			0		9			
7994-	1535-54			Acuff	Enterprise	s Inc.			1			
		L								•	1	
Legrify unde	er penalty of law	that this docum	ent and all a	ttachments v	vere	COG EPS	C Inspector	and Title (p	rint or type)	:	Signature:	
	der my direction					2 (2)		.,	. ,			lat
	assure that quali resented. Base					0	Gera	ld "Jerry" S	tanfill		Donal	Hants
	system, or those					Contractor	EPSC Insp	ector and T	ille (nrint or	tyne):	Signature:	son p
	cerify that inspe					Contractor	Lr 30 map	ector and r	ide (print or	type).	/ A	1 1
	d sediment cont tify that erosion a							Tom Acuff			1 /	
	fall where install										form We	un
recorded in the	he table above.	I am aware that	there are si	gnificant pena	alties for		COG EPSC Project Manager Signature:				16//	
	lse information,	including the po	ssibility of fi	ne and impre	sonment for	(print or ty	pe):				1 /-1/	
knowing viola	ations.						Timothy Bierdz				\\ \Dank(1) \  120	4
											10 /	/
		TDOT EPSO				Rainfall	Rainfall	Rainfall	1	TDOTICO	ntractor Agrees with I	henection Report:
Date	Day of Mook	Predicted	Rainfall	Rainfall Gauge 2	Rainfall Gauge 3	Gauge 4	Gauge 5	Gauge 6	Duration	NO	or (YES)	napodion report.
Date	Day of Week	Precipitation (%)	Gauge 1 (in)	(in)	(in)	(in)	(in)	(in)	(hr)		lain and initial;	
	Sunday	(,0)	(111)	()	N/A	N/A	N/A	N/A		Chmer	true aitema	n 17 Dutakes.
7/11/11	Monday	10	0	0	N/A	N/A	N/A	N/A		and s	and recesor	no actions are
7/12/11	Tuesday	30	0	0	N/A	N/A	N/A	N/A		in W	ork Longs that	Jane active.
7/13/11	Wednesday	40	0	0	N/A	N/A	N/A	N/A				<u> </u>
7/14/11	Thursday	40	0	0	N/A	N/A	N/A	N/A				
7/15/11	Friday	30			N/A	N/A	N/A	N/A				
7/16/11	Saturday	10			N/A	N/A	N/A	N/A				
7/17/11	Sunday	30			N/A	N/A	N/A	N/A				
7/18/11	Monday	0			N/A	N/A	N/A	N/A				
,										I (Ad	Iditional pages may be	e attached, if needed)

www.weather.com

State/US	Route	or Ro

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:

Date	7/14/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1	1	14+14	LT	6/3/2011		22,35	S	STABLE (NO ACTION NEEDED)
1A	1	21+50	RT	7/5/2011	T = 3-25-11	33,35	S	STABLE (NO ACTION NEEDED)
1B	1	22+00	RT	6/20/2011	T= 3-25-11	24,33,35	S	STABLE (NO ACTION NEEDED)
1C	1	21+00	LT	7/8/2011	T = 3-25-11	10,12,16,35	FM	The perimeter needs additional mulch. Once haul road is established.
2A	1	33+50	LT	7/14/2011		16,24	S	STABLE (NO ACTION NEEDED)
2B	1	35+50	LT	7/14/2011		16,24	I, RO	Incomplete, remove felled trees from stream and debris. See Photo
3	1	34+50	LT				S	The area has not been disturbed.
4	1	40+00	RT	7/14/2011		16	S	STABLE (NO ACTION NEEDED)
5A	1	49+00	RT				S	The area has not been disturbed.
5B	1	50+00	RT		27 200		S	The area has not been disturbed.

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

1	Temporary Silt Fence / Filter Barrier	15		29	Excess Dirt Removed from Rdwy. Daily	M	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	W	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42		Other (O#3):	

**EPSC Inspection** 

Page \_2\_\_of \_\_7\_

**CONDITION CODES** 

State/US	Route	or Ro

ate/US	Route	or Road	Name:	Wolf	River

TOOT	0		
111111	Lonsi	ruction	NO.

799		

	2	
TDOT	Contract No.:	•
1001	CUILLIAGE NO	·

**CONDITION CODES** 

Date	7/14/2011

Blvd.

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
5C	1	44+00	LT				S	The area has not been disturbed.
6	1	56+00	LT				S	The area has not been disturbed.
7	1	60+00	RT				S	The area has not been disturbed.
8A	1	73+00	RT				S	The area has not been disturbed.
8B	2	75+50	RT	7/5/2011	40	16,35	S	Stable (No action needed)
8C	1	71+00	LT				S	The area has not been disturbed.
8D	2	75+50	LT	7/5/2011		16,35	S	Stable (No action needed)
8E	1	71+50	LT		7.40		S	The area has not been disturbed.
9A	2	80+00	RT	7/11/2011		16,35	I,RO	Incomplete, stabilize. See Photo
9B	2	80+00	LT	7/11/2011		16,35	I,RO	Additional BMP's required. See Photo

### **EROSION AND SEDIMENT CONTROL MEASURE CODES**

### Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily М Maintenance Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 2 R 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FΜ **Future Maintenance** Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing С Cleaning Needed 5 Sediment Removal 20 34 Enhanced Silt Fence 6 Riprap Outlet Structure Increase Measures Straw Bale Check 21 35 Sediment Tube W 7 Riprap Energy / Velocity Dissipater Too Wet to Work Conditions Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 8 23 37 SR 9 Sediment Trap / Basin Temporary at Construction Exit / Entrance Concrete Washout, other pollution Issues Sediment Release Temp Sediment Filter Bag / Dewatering 38 10 24 **Temporary Stream Crossing** Berm (soil, riprap, rock) FS Final Stabilized Turbidity Barrier / Silt Boom 39 S 11 Polyethylene Sheeting 25 Gabion Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): 27 41 Haul Road Other (O#2): 13 Geotextile Preserve Natural Resource / Buffer Zone 42 Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade Other (O#3):

State/US	Doute or	Dood.	Mana
Sidle/US	Ruule of	Roau	maille.

Wolf River Blvd.

TDOT Construction No.: 79954-3537-54

TDOT Contract No.: \_

Date \_\_\_\_\_7/14/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	7/11/2011		16,35	I,RO	Additional BMP's Required. See Photo
10A	2	85+00	RT	7/11/2011	T = 5-31-11	16,24,35	S	Currently stable, Monitoring BMP's
10B	2	85+00	RT	7/11/2011	T = 5-31-11	16,24,35	S	Currently stable, Monitoring BMP's
10C	2	85+50	LT	7/8/2011	T = 5-31-11	16,35	M,RO	Incomplete, Remove construction floatables and stabilize. See Photo
10D	2	84+50	LT	7/8/2011	T = 5-31-11	10,16,35	I,RO	Stockpile too close to work zone/stream and stabilize.
11A	2	92+50	RT	7/14/2011	T = 5-31-11	16,24,35	FM	Remove temp. rock dam at end of each day after construction.
11B	2	92+50	LT	7/14/2011	T = 5-31-11	10,35	I,RO	Stockpile too close to work zone/stream and stabilize. See photo
11C	2	92+00	LT	7/14/2011	T = 5-31-11	35	I,RO	Incomplete, Stockpile too close to work zone/stream and stabilize. (See photo) Floatables have been removed from stream bed.
	1	11+28	LT	6/27/2011	T = 6-3-11	19,35	FM	Currently stable, Monitoring BMP's
	1	13+40	RT	7/5/2011		23,29,30	FM	Daily cleaning will be required, until further notice.
	1	107+75	CL	7/5/2011		23,29,30	FM	Daily cleaning will be required, until further notice.

EROSION AND SEDIMENT CONTROL MEASURE CODES CONDITI								
1	Temporary Silt Fence / Filter Barrier	15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	М	Maintenance	
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)	
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed	
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance	
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed	
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	18	Increase Measures	
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	W	Too Wet to Work Conditions	
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence	
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release	
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized	
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)	
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):		
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):		
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42		Other (O#3):	A	

ŕ

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:	

Date	7/14/2011

Outfall Name or Station No. *(Existing Structure)	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
* 109+51	2	East side of WRB	RT	7/5/2011		19,22	FM	Stable, monitoring BMP's.
* 109+11	2	South side of Farmington	RT	7/5/2011		19,22	FM	Stable, monitoring BMP's.
* 12+80	1	North side of WRB	LT	7/5/2011		19,22	FM	Stable, monitoring BMP's
	1	23+25	LT	7/5/2011			FM	Daily monitoring required.
		100000	11/1000-01-01-01					
	2	75+00	CL	7/11/2011		16	S	Currently stable, Monitoring BMP's.
	2	107+30 - 107+50	LT	7/14/2011		16,35,41	C,RO	Remove excess concrete. See Photo

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

### Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily M Maintenance Temporary Diversion Berm or Ditch 30 16 Temporary Mulch Haul Roads Dampened for Dust Control Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing С Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions Sand Bags Curb, Gutter, or Storm Sewer Protection 36 8 22 Sediment Dam RO Repeat Occurrence Sediment Trap / Basin Concrete Washout, other pollution Issues 9 23 Temporary at Construction Exit / Entrance 37 SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) Final Stabilized Polyethylene Sheeting 25 39 S 11 Turbidity Barrier / Silt Boom Gabion Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Other (O31): Sheet Pilling Other (O#2): \_\_\_\_ 27 13 Geotextile Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#3): Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade 42

**CONDITION CODES** 

EPSC Inspection Page <u>5</u> of 7\_



Outfall 2B Sta. 35+50 LT Remove felled trees and debris from stream. (I,RO)



Outfall 9A Sta. 80+00 RT Incomplete, stabilize. (I,RO)




Outfall 9B Sta. 80+00 LT and Outfall 9C Sta.79+50 LT Additional BMP's required. (I,RO)



Outfall 10C Sta. 85+50 LT Remove construction floatables and stabilize (M,RO)





No Picture

Sta. 107+30 – 107+50 LT Remove excess concrete (C,RO)

